

To: Leonard Pimm[bowlen300@aol.com];
greg@rapidsbowlingcenter.com[greg@rapidsbowlingcenter.com]; William Burg[wburg@gnbcsupply.com]
From: Daly, Eric
Sent: Thur 5/26/2016 11:45:42 AM
Subject: Re: Niagara Falls Boulevard Site-Rapids/GNBC

Good Morning. I did forget to ask you about the GNBC office area door. We would like to open that up to get our equipment in and out. We wanted owner/operator opinion on that. Are we keeping the vestibule? Install double doors? Could you please take a photo of the door so we can do some preliminary discussion?

Thanks

Regards,

Eric

"We must, indeed, all hang together, or assuredly we shall all hang separately", Benjamin Franklin
Eric M. Daly
On-Scene Coordinator/Radiological Response Specialist
US Environmental Protection Agency- Region II

ERRD/RPB/PPS
2890 Woodbridge Avenue
Edison, NJ 08837
daly.eric@epa.gov
732-321-4350

On May 25, 2016, at 6:17 PM, Daly, Eric <Daly.Eric@epa.gov> wrote:

Good Evening:

Thanks for taking the time to talk yesterday. Attached is a copy of the presentation we went over.

Clarification, we are traveling to the Niagara Falls area on Tuesday, May 31st. Our first day on Site is Wednesday, June 1st. I keep forgetting about the holiday on Monday.

Lastly, if you haven't already emailed me, please send me the information for the additionally insured request. Exact property address/SBL info and exact owner information to be listed.

Thanks

Regards,

Eric

"We must, indeed, all hang together, or assuredly we shall all hang separately", Benjamin Franklin

Eric M. Daly

On-Scene Coordinator/Radiological Response Specialist

US Environmental Protection Agency- Region II

ERRD/RPB/PPS

2890 Woodbridge Avenue

Edison, NJ 08837

daly.eric@epa.gov<<mailto:daly.eric@epa.gov>>

732-321-4350

<NFB Presentation GNBC.pdf>